(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	absorption fields		Sewage lagoons	joons	
		Rating class and limiting features	Value	Rating class and limiting features	Value	
26: Kennebec	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 0.71 0.50	
27B: Terril	100	Somewhat limited Depth to saturated zone restricted permeability	0.43	Somewhat limited Seepage Slope	0.50	
27C: Terril	90	Somewhat limited Depth to saturated zone restricted permeability	0.43	Very limited Slope Seepage	1.00	
31: Afton	95	Very limited Flooding Depth to saturated zone Restricted permeability	1.00 1.00 0.91	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 0.32	
32: Spicer	90	Very limited Depth to saturated zone restricted permeability	1.00	Very limited Depth to saturated zone Seepage	1.00	
72B: Estherville	95	Very limited Filtering capacity	1.00	Very limited Seepage Slope	1.00	

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Septic tank absorption field	ds	Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
72D: Estherville	100	Very limited Filtering capacity Slope	1.00	Very limited Seepage Slope	1.00
73E: Salida	85	Very limited Filtering capacity Slope	1.00	Very limited Slope Seepage	1.00
73F: Salida	95	Very limited Filtering capacity Slope	1.00	Very limited Slope Seepage	1.00
77B: Sac	90	Not limited restricted permeability	0.25	Somewhat limited Seepage Slope	0.50
77C2: Sac	90	Not limited restricted permeability	0.25	Very limited Slope Seepage	1.00
89B: Sac Variant	100	Not limited restricted permeability	0.25	Somewhat limited Seepage Slope	0.50
89C2: Sac Variant	90	Not limited restricted permeability	0.25	Very limited Slope Seepage	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	absorption fields		Sewage lagoons	1	
		Rating class and limiting features	Value	Rating class and limiting features	Value	
91: Primghar	95	Very limited Depth to saturated zone restricted permeability	1.00	Somewhat limited Depth to saturated zone Seepage	0.71	
91B: Primghar	95	Very limited Depth to saturated zone restricted permeability	1.00	Somewhat limited Depth to saturated zone Seepage Slope	0.71	
92: Marcus	90	Very limited Depth to saturated zone Restricted permeability	1.00	Very limited Depth to saturated zone Seepage	1.00	
133: Colo	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 0.50	
202: Cylinder	90	Very limited Filtering capacity Depth to saturated zone restricted permeability	1.00	Very limited Seepage Depth to saturated zone	1.00	

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
203: Cylinder	90	Very limited Filtering capacity Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Seepage Depth to saturated zone	1.00
259: Biscay	95	Very limited Depth to saturated zone Filtering capacity restricted permeability	1.00 1.00 0.25	Very limited Depth to saturated zone Seepage	1.00
282: Ransom	95	Very limited Depth to saturated zone Restricted permeability	1.00	Very limited Depth to saturated zone Seepage	0.92
310: Galva	90	Not limited restricted permeability	0.25	Somewhat limited Seepage	0.50
310B: Galva	90	Not limited restricted permeability	0.25	Somewhat limited Seepage Slope	0.50
310C2: Galva	95	Not limited restricted permeability	0.25	Very limited Slope Seepage	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Septic tank absorption fiel	ds	Sewage lagoons	ge lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value	
311: Galva	98	Very limited Filtering capacity restricted permeability	1.00	Somewhat limited Seepage	0.50	
311B: Galva	92	Very limited Filtering capacity restricted permeability	1.00	Somewhat limited Seepage Slope	0.50	
433D: Storden	95	Somewhat limited Slope restricted permeability	0.63	Very limited Slope Seepage	1.00	
433E: Storden	85	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00	
433F: Storden	95	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00	
433G: Storden	100	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00	
474B: Bolan	85	Very limited Filtering capacity	1.00	Very limited Seepage Slope	1.00	

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons		
		Rating class and limiting features	Value	Rating class and limiting features	Value	
474C: Bolan	85	Very limited Filtering capacity Slope	1.00	Very limited Seepage Slope	1.00	
485: Spillville	85	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Seepage Depth to saturated zone	1.00	
505: Sperry	100	Very limited Depth to saturated zone Restricted permeability	1.00	Very limited Depth to saturated zone	1.00	
577C2: Everly	85	Not limited restricted permeability	0.25	Very limited Slope Seepage	1.00	
577D: Everly	85	Somewhat limited Slope restricted permeability	0.63	Very limited Slope Seepage	1.00	
639G: Storden	55	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00	
Salida	40	Very limited Filtering capacity Slope	1.00	Very limited Slope Seepage	1.00	

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Septic tank absorption fiel	ds	Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
708B: Fairhaven	85	Very limited Filtering capacity restricted permeability	1.00	Very limited Seepage Slope	1.00
708C2: Fairhaven	95	Very limited Filtering capacity restricted permeability	1.00	Very limited Seepage Slope	1.00
709: Fairhaven	95	Very limited Filtering capacity restricted permeability	1.00	Very limited Seepage	1.00
709B: Fairhaven	85	Very limited Filtering capacity restricted permeability	1.00	Very limited Seepage Slope	1.00
733: Calco	100	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Depth to saturated zone Seepage	1.00
785: Spillco	85	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Depth to saturated zone	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	absorption fields		Sewage lagoons	ons	
		Rating class and limiting features	Value	Rating class and limiting features	Value	
878B: Ocheyedan	85	Not limited restricted permeability	0.25	Somewhat limited Seepage Slope	0.50	
1658C: Terril	50	Somewhat limited Depth to saturated zone restricted permeability	0.43	Very limited Slope Seepage	0.91	
Colo	45	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage Slope	1.00 1.00 0.50 0.33	
1785: Spillco	90	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone	1.00	
5010: Pits	95	Not rated		Not rated		
5040: Orthents	90	Not rated		Not rated		